

University of Nebraska - Lincoln

DigitalCommons@University of Nebraska - Lincoln

Architectural Engineering -- Faculty Publications

Architectural Engineering and Construction,
Durham School of

2018

SDNET2018: An annotated image data set for non-contact concrete crack detection using deep convolutional neural networks

Sattar Dorafshan

Utah State University, sattar.dor@aggiemail.usu.edu

Robert J. Thomas

Clarkson University, rthomas@clarkson.edu

Marc Maguire

Utah State University, m.maguire@usu.edu

Follow this and additional works at: <https://digitalcommons.unl.edu/archengfacpub>



Part of the [Architectural Engineering Commons](#), [Construction Engineering Commons](#), [Environmental Design Commons](#), and the [Other Engineering Commons](#)

Dorafshan, Sattar; Thomas, Robert J.; and Maguire, Marc, "SDNET2018: An annotated image data set for non-contact concrete crack detection using deep convolutional neural networks" (2018). *Architectural Engineering -- Faculty Publications*. 162.

<https://digitalcommons.unl.edu/archengfacpub/162>

This Article is brought to you for free and open access by the Architectural Engineering and Construction, Durham School of at DigitalCommons@University of Nebraska - Lincoln. It has been accepted for inclusion in Architectural Engineering -- Faculty Publications by an authorized administrator of DigitalCommons@University of Nebraska - Lincoln.



Contents lists available at ScienceDirect

Data in Brief

journal homepage: www.elsevier.com/locate/dib



Data Article

SDNET2018: An annotated image dataset for non-contact concrete crack detection using deep convolutional neural networks



Sattar Dorafshan^{a,*}, Robert J. Thomas^b, Marc Maguire^a

^a Department of Civil and Environmental Engineering, Utah State University, Logan, Utah, USA

^b Department of Civil and Environmental Engineering, Clarkson University, Potsdam, NY, USA

ARTICLE INFO

Article history:

Received 18 May 2018

Received in revised form

15 August 2018

Accepted 2 November 2018

ABSTRACT

SDNET2018 is an annotated image dataset for training, validation, and benchmarking of artificial intelligence based crack detection algorithms for concrete. SDNET2018 contains over 56,000 images of cracked and non-cracked concrete bridge decks, walls, and pavements. The dataset includes cracks as narrow as 0.06 mm and as wide as 25 mm. The dataset also includes images with a variety of obstructions, including shadows, surface roughness, scaling, edges, holes, and background debris. SDNET2018 will be useful for the continued development of concrete crack detection algorithms based on deep convolutional neural networks (DCNNs), which are a subject of continued research in the field of structural health monitoring. The authors present benchmark results for crack detection using SDNET2018 and a crack detection algorithm based on the AlexNet DCNN architecture. SDNET2018 is freely available at <https://doi.org/10.15142/T3TD19>.

© 2018 The Authors. Published by Elsevier Inc. This is an open access article under the CC BY license (<http://creativecommons.org/licenses/by/4.0/>).

* Corresponding author.

E-mail addresses: sattar.dor@aggiemail.usu.edu (S. Dorafshan), rthomas@clarkson.edu (R.J. Thomas), m.maguire@usu.edu (M. Maguire).

<https://doi.org/10.1016/j.dib.2018.11.015>

2352-3409/© 2018 The Authors. Published by Elsevier Inc. This is an open access article under the CC BY license (<http://creativecommons.org/licenses/by/4.0/>).

Specifications table

Subject area	Structural health monitoring, deep learning, convolutional neural networks, artificial intelligence
More specific subject area	Concrete crack detection, image classification
Type of data	2D-RGB image (.jpg)
How data was acquired	Original images of cracked and non-cracked concrete bridge decks, walls, and pavements were captured using a 16 MP Nikon digital camera.
Data format	Raw digital images (.jpg)
Experimental factors	
Experimental features	<ul style="list-style-type: none"> • 230 images of cracked and non-cracked concrete (54 bridge decks, 72 walls, 104 pavements) segmented into more than 56,000 sub-images (256 × 256 px) • Crack widths from 0.06 to 25 mm • Obstructions including shadows, surface debris, inclusions, scaling, etc...
Data source location	Utah State University, Logan, Utah, USA
Data accessibility	The dataset is freely accessible at [1] for any academic purposes
Related research article	Parts of this dataset have been used in the following research items for image-based non-contact crack detection applications: [2–8]

Value of the data

- SDNET2018 can be used for training, validation, and benchmarking of algorithms for autonomous crack detection in concrete;
- SDNET2018 has images of reinforced concrete decks (D) and walls (W), and unreinforced concrete pavements (P), which enables DCNNs training on it while also categorizing different types of concrete cracks;
- A DCNN trained on SDNET2018 can identify fine and wide cracks due to the size variety in it, widths from 0.06 mm to 25 mm;
- Images in SDNET2018 intentionally include irrelevant objects which may improve the accuracy of DCNNs trained on this dataset in real applications;
- SDNET2018 can be used to develop new DCNN architectures or modify the existing architectures, e.g. AlexNet or GoogleNet, in order to increase the efficiency of the network for concrete crack detection.

1. Data

The SDNET2018 image dataset contains more than 56,000 annotated images of cracked and non-cracked concrete, bridge decks, walls, and pavements. Its purpose is for training, validation, and benchmarking of autonomous crack detection algorithms based on image processing, deep convolutional neural networks (DCNN) [8], or other techniques. Such techniques are increasing in popularity in the structural health monitoring field. Continued advancement of crack detection algorithms requires an annotated diverse image dataset [9], which has not been available until now.

Images of bridge decks were taken at the Systems, Materials, and Structural Health (SMASH) Laboratory at Utah State University, where a number of full scale bridge deck sections were stored. Images of walls and pavements were taken on Utah State University campus. Table 1 lists the number of cracked, non-cracked, and total sub-images of each type included in SDNET2018. The sample images in Fig. 1 show the range of crack widths, surface conditions, and other environmental factors represented within SDNET2018. Images are 256 × 256-px RGB image files in .jpg format. Each image

Table 1
SDNET2018 image dataset description and statistics.

Image description		No. cracked	No. non-cracked	Total
Reinforced	Bridge deck	2025	11,595	13,620
	Wall	3851	14,287	18,138
Unreinforced	Pavement	2608	21,726	24,334
Total		8484	47,608	56,092



Fig. 1. SDNET2018 images include (a) fine cracks, (b) coarse cracks, (c) shadows, (d) stains, (e) rough surface finishes, (f) inclusions and voids, (g) edges, (h) joints and surface scaling, and (i) background obstructions.

Table 2
Benchmark for SDNET2018 image classification using AlexNet.

Image description	No. sub-images		DCNN mode	Training epochs	Accuracy (%)
	Training	Testing			
Bridge deck	12,259	1,361	FT	32	90.45
			TL	10	91.92
Wall	16,324	1,814	FT	30	87.54
			TL	9	89.31
Pavement	21,900	2,434	FT	30	94.86
			TL	10	95.52

is classified as cracked or non-cracked and stored in a corresponding folder within the repository. Images are organized into three sub-directories: P for pavements, W for walls, and D for bridge decks. Each subfolder is further organized into sub-sub-directories with the prefix C for cracked and U for uncracked (e.g., D/CD for images of bridge decks with cracks). With the exception of segmentation into sub-images as discussed above, the images have not been modified from their original state.

2. Experimental design, materials, and methods

SDNET2018 images were taken with a 16-MP Nikon camera at a working distance of 500 mm without zoom. The sensitivity was 125 ISO and the image resolution was 4068×3456 px. The surface illumination was between 1500 and 3000 lx. Each full image was segmented into 256×256 -px sub-images. Each image represents a physical area of approximately $1000 \text{ mm} \times 850 \text{ mm}$ and each sub-image represents a physical area of approximately $60 \text{ mm} \times 60 \text{ mm}$. The authors analyzed the SDNET2018 dataset using the AlexNet DCNN architecture in fully trained (FT) and transfer learning (TL) modes using the computational setup and procedure described by Dorafshan et al. [8]. Benchmarking results, including the sizes of the training and testing datasets, number of epochs required for training, and accuracy of classification of the testing dataset, are presented in Table 2.

Transparency document. Supporting information

Transparency data associated with this article can be found in the online version at <https://doi.org/10.1016/j.dib.2018.11.015>.

References

- [1] M., Maguire, S., Dorafshan, R.J., Thomas, SDNET2018: A concrete crack image dataset for machine learning applications. Browse all Datasets. Paper 48. (https://digitalcommons.usu.edu/all_datasets/48). (<https://doi.org/10.15142/T3TD19>). (Accessed 18 May 2018).
- [2] S. Dorafshan, M. Maguire, Autonomous detection of concrete cracks on bridge decks and fatigue cracks on steel members, in: Proceedings of Digital Imaging 2017, Mashantucket, CT, 2017.
- [3] S. Dorafshan, M. Maguire, M. Chang, Comparing automated image-based crack detection techniques in spatial and frequency domains, in: Proceedings of the 26th American Society of Nondestructive Testing Research Symposium, Jacksonville, FL, 2017.
- [4] S. Dorafshan, M. Maguire, N. Hoffer, C. Coopmans Challenges in bridge inspection using small unmanned aerial systems: results and lessons learned, in: Proceedings of the 2017 International Conference on Unmanned Aircraft Systems, Miami, FL, 2017. (<http://dx.doi.org/10.1109/ICUAS.2017.7991459>).
- [5] S. Dorafshan, M. Maguire, M. Chang, Comparing automated image-based crack detection techniques in spatial and frequency domains, in: Proceedings of the 26th American Society of Nondestructive Testing Research Symposium, Jacksonville, FL, 2017. (<http://dx.doi.org/10.1109/ICUAS.2017.7991459>).
- [6] S. Dorafshan, C. Coopmans, R. Thomas, M. Maguire, Deep learning neural networks for sUAS-assisted structural inspections, feasibility and application, in: Proceedings of ICUAS 2018, Dallas, TX, 2018. DOI: <https://doi.org/10.1109/ICUAS.2018.8453409>.

- [7] S. Dorafshan, M. Maguire, X. Qi, Automatic Surface Crack Detection in Concrete Structures Using OTSU Thresholding and Morphological Operations, Civil and Environmental Engineering Faculty Publications, Utah State University, Logan, Utah, 2016, Paper 1234.
- [8] S. Dorafshan, R.J. Thomas, M. Maguire, Comparison of deep convolutional neural networks and edge detectors for image-based crack detection in concrete, *Constr. Build. Mater.* 186 (2018) 1031–1045.
- [9] F.S. Bashiri, E. LaRose, P. Peissig, A.P. Tafti, MCIndoor20000: a fully-labeled image dataset to advance indoor objects detection, *Data Brief* 17 (2018) 71–75.